



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

| Engine Rotor Sheet | | | | | | | |
|---------------------------|---------------|------|----------------------------------|------|---------------------------------|-------|--------------|
| PT6A: | -114A | TSN: | 7,041.8 | TSO: | 3,267.7 | W/O#: | 9655 |
| PCE: | PC1002 | CSN: | Starts: 8,183 Flights: 14,189 | CSO: | Starts: 3,465 Flights: 5,940 | TSHS: | 329.3 |

| Life Limited Part (LLP) Listing | | | | |
|--|---------|----------|----------|-----------|
| | P/N | S/N | Cycles | |
| | | | Consumed | Remaining |
| Hub, 1 st Stg. | 3013111 | 77B126 | 11,186 | 7,814 |
| Disk, 2 nd Stg. | 3013712 | A0017805 | 11,186 | 12,814 |
| Disk, 3 rd Stg. | 3011713 | A00177YB | 11,186 | 13,814 |
| Impeller | 3027798 | TX1A2322 | 11,186 | 7,814 |
| Disk, CT | 3013411 | A0017L8W | 9,384 | 6,616 |
| PT Disk, 1 st Stg. | 3026812 | A0017R3C | 9,384 | 10,616 |

Key: TBA = To be assigned, N/A = Not Applicable

| Accessories | | | |
|--------------------|-------------|----------|---------|
| | P/N | S/N | TSO |
| PROPELLER GOVERNOR | 8210-002-01 | 13296411 | 3,267.7 |
| FUEL PUMP | 702801-5 | 000742 | 3,267.7 |
| FUEL CONTROL UNIT | 3244897-4 | C65589 | 3,267.7 |
| FLOW DIVIDER | 25536-4 | 21002 | 3,267.7 |
| OIL/FUEL HEATER | 10552E | WA18700 | 3,267.7 |
| COMP. BLEED VALVE | 540-1407-4 | 3354 | 3,267.7 |

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.