



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-114A	TSN:	12,732.5	TSO:	1,865.9	W/O#:	TBT
PCE:	17405	CSN:	14,576	CSO:	2,486	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	1Y637	14,576	4,424
Disk, 2 nd Stg.	3013712	1A890	20,233	3,767
Disk, 3 rd Stg.	3011713	6487	21,388	3,612
Impeller	3027798	7E420	16,217	2,783
Disk, CT	3013411	5D968	13,633	2,367
PT Disk, 1 st Stg.	3026812	23B801	19,848	152
Key: TBA = To be assigned, N/A = Not Applicable				

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	2476713	1,865.9
FUEL PUMP	702801-5	0249	1,865.9
FUEL CONTROL UNIT	3244809-8	C25593	3,592.9
FLOW DIVIDER	3019906/25536-4	12855	1,865.9
OIL/FUEL HEATER	10552E	1276	1,865.9
COMP. BLEED VALVE	3049038-03	GA1151	1,865.9
Key: TBA = To be assigned, N/A = Not Applicable			

Comments: All engines ship FOB ATS dock.