



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-27/-28	TSN:	3,774.17	TSO:	2,177.17	W/O#:	7439
PCE:	52434	CSN:	3,825	CSO:	2,337	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	1F534	3,825	15,175
Disk, 2 nd Stg.	3043712	3H548	3,825	20,175
Disk, 3 rd Stg.	3011713	5F609	3,825	21,175
Impeller	3013176	3D514	3,825	15,175
Disk, CT	3013411	1F119	3,825	12,175
PT Disk, 1 st Stg.	3022412	1F047	3,825	16,175

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-001-01	1577944	1,965.1
FUEL PUMP	025323-150	1043	1,601.9
FUEL CONTROL UNIT	3244786-3	B32133	2,111.6
START FLOW CONTROL	3019109	9251	1,618.1
OIL/FUEL HEATER	10552E	2788	1,618.1
COMP. BLEED VALVE	3100829-03	9E583	1,601.9

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.