



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-27/-28	TSN:	10,082	TSO:	0.0	W/O#:	7433
PCE:	PG0193	CSN:	14,567	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	77B129	14,567	4,433
Disk, 2 nd Stg.	3013712	A00166WE	14,567	9,433
Disk, 3 rd Stg.	3011713	A00166WX	14,567	10,433
Impeller	3013176	8H567	14,567	4,433
Disk, CT	3013411	A7164	11,562	4,438
PT Disk, 1 st Stg.	3026812	A0016T20	14,567	5,433

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-004U	1158234	0.0
FUEL PUMP	386101-5	001691	0.0
FUEL CONTROL UNIT	2524440	A41903	0.0
START FLOW CONTROL	3019109	9734	0.0
OIL/FUEL HEATER	10552E	8809	0.0
COMP. BLEED VALVE	3100829-03	AHX001571	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.