



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

<b>Engine Rotor Sheet</b>							
PT6A:	<b>-34AG</b>	TSN:	<b>16,279.15</b>	TSO:	<b>0.0</b>	W/O#:	<b>6798</b>
PCE:	<b>57462</b>	CSN:	<b>27,140</b>	CSO:	<b>0.0</b>	TSHS:	<b>0.0</b>

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3013111	8978	13,097	5,903
Disk, 2 <sup>nd</sup> Stg.	3013712	7633	16,853	7,147
Disk, 3 <sup>rd</sup> Stg.	3011713	3468	17,929	7,071
Impeller	3032249	2B144	10,297	8,703
Disk, CT	3013411	30A346	11,000	5,000
PT Disk, 1 <sup>st</sup> Stg.	3022412	2F786	14,913	5,087

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-003	1451912	0.0
FUEL PUMP	386100	002484	0.0
FUEL CONTROL UNIT	3244834-4-3-2	A41245	0.0
START FLOW CONTROL	3019109	6708	0.0
OIL/FUEL HEATER	10552E	296	0.0
COMP. BLEED VALVE	3100829-03	J46224	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.