



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-42	TSN:	10,307.9	TSO:	3,487.5	W/O#:	7738
PCE:	93709	CSN:	8,050	CSO:	2,388	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3041501	53A458	5,407	24,593
Disk, 2 nd Stg.	3023112	2M070	8,050	11,950
Disk, 3 rd Stg.	3023113	A001CD4T	2,388	17,612
Impeller	3017463	7B556	8,050	11,950
Disk, CT	3049291-01	A001L631	2,946	7,054
PT Disk, 1 st Stg.	3022812	2E115	7,520	480
PT Disk, 2 nd Stg.	3022813	5D082	6,786	1,214

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-024H	19947600H	3,487.5
FUEL PUMP	025323-300-03	8909	3,487.5
FUEL CONTROL UNIT	3244768-13-12-11-10-9-8-7	A69427	3,487.5
OIL/FUEL HEATER	10585	378	UNKNOWN
COMP. BLEED VALVE	3100922-05	A7054	3,487.5
COMP. BLEED VALVE	3100923-02	2F425	3,487.5

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.