



Airforce Turbine Service

Tel: (201) 446-7094

Fax: (760) 465-6755

Paul Callahan

E-Mail: pcallahan@aaenginesolutions.com

Engine Exhibit:



Engine Type & Model: PW118B

ESN : 115084

BS : 901

TSN: 38,620.8

TSO: 3,518.2

CSN: 49,518

CSO: 4,127

HSI: 0

TSLR: 0

CSLR: 0

Part #	Description	Life Limit	Since New	Remaining
3040689	LP Impeller	25,000	5,692	19,308
3043294	HP Impeller	15,000	3,423	11,577
3039640	HP Front Cover	15,000	5,588	9,412
3039639	HP Rear Cover	15,000	4,127	10,873
3041511	HP Turbine Disk	15,000	4,127	10,873
3039172	Interstage Seal	15,000	4,127	10,873
3036412	LP Turbine Disk	15,000	6,880	18,120
3038613	PT Disk, Stage 1	30,000	1,466	28,534
3033914	PT Disk, Stage 2	30,000	1,466	28,534
3115601-01	HP Blades	15,000	4,127	10,873

PT 1 Blades TSN: 8,664.6

LP Blades Time Since Creep Check: 3,516.6

#4 Bearing TSN: 486.2

Last OH by Standard Aero

Last HIS by Dallas Airmotive (current shop visit)

O (361) 547-3386

F (361) 547-7273

W www.pt6a.aero

STREET ADDRESS

11557 Highway 359

Mathis, TX 78368

MAILING ADDRESS

P.O. Box 146

Tynan, TX 78391

**F.A.A. APPROVED
REPAIR STATION**

C.R.S. TQZR133K