



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-27I-28	TSN:	7,515.1	TSO:	0.0	W/O#:	7985
PCE:	42419	CSN:	12,297	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	1R916	11,002	7,998
Disk, 2 nd Stg.	3013712	2R658	11,002	12,998
Disk, 3 rd Stg.	3011713	1R508	11,002	13,998
Impeller	3013176	4D525	4,644	14,356
Disk, CT	3013411	6940	5,549	10,451
PT Disk, 1 st Stg.	3022412	8A435	7,420	12,580

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-003	1821859U	0.0
FUEL PUMP	025323-101	5534	0.0
FUEL CONTROL UNIT	32440-7-6	A75559	0.0
START FLOW CONTROL	3019109	10427	0.0
OIL/FUEL HEATER	10552E	4471	0.0
COMP. BLEED VALVE	3100829-03	9F058	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.