



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-27I-28	TSN:	6,211	TSO:	1,829.5	W/O#:	8224
PCE:	42651	CSN:	3,807	CSO:	1,567	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	24A980	3,807	15,193
Disk, 2 nd Stg.	3013712	52A849	3,807	20,193
Disk, 3 rd Stg.	3011713	52A908	3,807	21,193
Impeller	3013176	7D396	3,807	15,193
Disk, CT	3013411	7981	4,806	11,194
PT Disk, 1 st Stg.	3022412	55A616	3,807	16,193

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-004U	1999004	1,829.5
FUEL PUMP	025323-101-03	7278	1,829.5
FUEL CONTROL UNIT	2524440-7-6	TBA	2,333.8
START FLOW CONTROL	3019109	11589	2,333.8
OIL/FUEL HEATER	10552E	1045	1,829.5
COMP. BLEED VALVE	3100829-03	10A555	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.