



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

<b>Engine Rotor Sheet</b>							
PT6A:	<b>-34</b>	TSN:	<b>27,025.0</b>	TSO:	<b>3,033.0</b>	W/O#:	<b>8611</b>
PCE:	<b>40113</b>	CSN:	<b>45,420</b>	CSO:	<b>4,967</b>	TSHS:	<b>0.0</b>

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3013111	9C948	8,378	10,622
Disk, 2 <sup>nd</sup> Stg.	3013712	7B856	13,148	10,852
Disk, 3 <sup>rd</sup> Stg.	3011713	4R519	10,809	14,191
Impeller	3013176	6A120	6,970	12,030
Disk, CT	3013411	A00086FF	6,882	9,118
PT Disk, 1 <sup>st</sup> Stg.	3026812	9W191	11,577	8,423

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-004-01	2701276	2,572.9
FUEL PUMP	025323-101-03	13426	3,033.0
FUEL CONTROL UNIT	2524440-7-6	A25771	1,334.1
START FLOW CONTROL	3019109	7558	1,436.0
OIL/FUEL HEATER	10552E	2959	3,033.0
COMP. BLEED VALVE	3100829-03	A9406	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.