



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-27I-28	TSN:	16,557.3	TSO:	2,193.3	W/O#:	8902
PCE:	51024	CSN:	15,965	CSO:	1,830	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	0234	15,965	3,035
Disk, 2 nd Stg.	3013712	A0525	15,965	8,035
Disk, 3 rd Stg.	3011713	8908	15,965	9,035
Impeller	3013176	A1994	15,965	3,035
Disk, CT	3013411	4B083	13,499	2,501
PT Disk, 1 st Stg.	3022412	17A769	15,965	4,035

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-003	1190445	0.0
FUEL PUMP	025323-101-03	5843	2,193.3
FUEL CONTROL UNIT	2524440-7-6	A59891	2,193.3
START FLOW CONTROL	25234-2	8467	2,193.3
OIL/FUEL HEATER	10552E	2226	2,193.3
COMP. BLEED VALVE	3075033-01	A9886	2,193.3

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.