



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

<b>Engine Rotor Sheet</b>							
PT6A:	<b>-42</b>	TSN:	<b>10,514.5</b>	TSO:	<b>3,545.1</b>	W/O#:	<b>8882</b>
PCE:	<b>93112</b>	CSN:	<b>13,192</b>	CSO:	<b>4,200</b>	TSHS:	<b>0.0</b>

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3053921-01	TXA1B0335	4,200	15,800
Disk, 2 <sup>nd</sup> Stg.	3023112	4F988	13,192	6,808
Disk, 3 <sup>rd</sup> Stg.	3023113	4F060	13,192	6,808
Impeller	3017463	9A998	13,192	6,808
Disk, CT	3049291-01	A0025TYT	4,200	5,800
PT Disk, 1 <sup>st</sup> Stg.	3058922-01	A00251BK	4,200	3,800
PT Disk, 2 <sup>nd</sup> Stg.	3058923-01	A002429F	4,200	3,800

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-007G	1744343	3,545.1
FUEL PUMP	025323-300-03	8248	3,545.1
FUEL CONTROL UNIT	3244768-13	A69199	3,545.1
OIL/FUEL HEATER	10585K-FGHJ	1334	3,545.1
LP COMP. BLEED VALVE	3100923-02	2A297	3,545.1
HP COMP. BLEED VALVE	3100922-05	1A592	3,545.1

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.