



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

| Engine Rotor Sheet | | | | | | | |
|---------------------------|--------------|------|-----------------|------|------------|-------|------------|
| PT6A: | -34 | TSN: | 10,441.5 | TSO: | 0.0 | W/O#: | TBA |
| PCE: | 51636 | CSN: | 12,132 | CSO: | 0.0 | TSHS: | 0.0 |

| Life Limited Part (LLP) Listing | | | | |
|--|---------|-------|----------|-----------|
| | P/N | S/N | Cycles | |
| | | | Consumed | Remaining |
| Hub, 1 st Stg. | 3013111 | 2A150 | 12,132 | 6,868 |
| Disk, 2 nd Stg. | 3013712 | 1A861 | 12,132 | 11,868 |
| Disk, 3 rd Stg. | 3011713 | 1A635 | 12,132 | 12,868 |
| Impeller | 3013176 | 1A046 | 12,132 | 6,868 |
| Disk, CT | 3013411 | 1A045 | 12,132 | 3,868 |
| PT Disk, 1 st Stg. | 3022412 | 2A319 | 12,132 | 7,868 |

Key: TBA = To be assigned, N/A = Not Applicable

| Accessories | | | |
|--------------------|---------------|---------|-----|
| | P/N | S/N | TSO |
| PROPELLER GOVERNOR | 8210-003-01 | 1495653 | 0.0 |
| FUEL PUMP | 025323-101-03 | 103D | 0.0 |
| FUEL CONTROL UNIT | 2524440-9 | A7406 | 0.0 |
| START FLOW CONTROL | 3019109A | 7636 | 0.0 |
| OIL/FUEL HEATER | 10552E | 4722 | 0.0 |
| COMP. BLEED VALVE | 3100829-03 | 3A306 | 0.0 |

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.