



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

<b>Engine Rotor Sheet</b>							
PT6A:	-21	TSN:	GG: 1,877.7 PS: 1,877.7	TSO:	GG: N/A PS: 741.7	W/O#:	<b>10970</b>
PCE:	PE0663	CSN:	GG: 1,864 PS: 1,864	CSO:	GG: N/A PS: 819	TSHS:	<b>333.9</b>

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3013111	RWA14A062	1,864	17,136
Disk, 2 <sup>nd</sup> Stg.	3013712	A001RKPE	1,864	22,136
Disk, 3 <sup>rd</sup> Stg.	3011713	A001T027	1,864	23,136
Impeller	3013176	EAAA000L518	1,864	17,136
Disk, CT	3013411	A001T9W3	1,864	14,136
PT Disk, 1 <sup>st</sup> Stg.	3026812	A001RTH1	1,864	18,136

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	66503-8210-025-01	17289857	UNKNOWN
FUEL PUMP	386101-5	002316	1,877.7
FUEL CONTROL UNIT	3244775-7 RE24	C21049	1,877.7
FLOW DIVIDER	3019906	6917	UNKNOWN
OIL/FUEL HEATER	10552E	WA22628	1,877.7
COMP. BLEED VALVE	3100829-03	1R268	741.7

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.