



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-65B	TSN:	GG: 27,078.1 PS: 25,963.0	TSO:	GG: 7,289.6 PS: 7,289.6	W/O#:	8785
PCE:	GG: 32199 PS: 32296	CSN:	GG: 29,176 PS: 27,922	CSO:	GG: 7,445 PS: 7,445	TSHS:	1,495.2

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Disk, 1 st Stg.	3033601	TXA1C6423	4,199	19,801
Disk, 2 nd Stg.	3033512	22B266	11,633	12,367
Disk, 3 rd Stg.	3033513	33B102	11,633	12,367
Disk, 4 th Stg.	3033514	32B713	11,633	12,367
Spacer, 4 th Stg.	3114590-01	21B066	11,633	12,367
Impeller	3036897	4E185	16,615	7,385
Disk, CT	3040311	15B916	12,020	2,980
PT Disk, 1 st Stg.	3029312	52B358	11,567	18,433
PT Disk, 2 nd Stg.	3029313	93A813	13,488	16,512

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-310B	2250551	7,289.6
FUEL PUMP	025323-500	264	7,289.6
FUEL CONTROL UNIT	Not Received	N/A	N/A
OIL/FUEL HEATER	Unknown	Unknown	Unknown
COMP. BLEED VALVE	3059831-01	7P164	Unknown

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.