



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

**ATS Form# 1024**

<b>Engine Rotor Sheet</b>							
PT6A:	-34	TSN:	2,480.4	TSO:	NA	W/O#:	11253
PCE:	RB0078	CSN:	2,640	CSO:	NA	TSHS:	544.5

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3013111	61B797	2,640	16,360
Disk, 2 <sup>nd</sup> Stg.	3013712	A000CW28	2,640	21,360
Disk, 3 <sup>rd</sup> Stg.	3011713	A000D3P4	2,640	22,360
Impeller	3013176	5H359	2,640	16,360
Disk, CT	3013411	A000CW28	2,640	13,360
PT Disk, 1 <sup>st</sup> Stg.	3026812	A000DBXB	2,640	17,360
Key: TBA = To be assigned, N/A = Not Applicable				

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	3035927	12198692U	2,480.4
FUEL PUMP	3034794	1326	2,480.4
FUEL CONTROL UNIT	252440-9-8-6	A7031	2,408.4
START FUEL CONTROL	3019109	15318	2,480.4
OIL/FUEL HEATER	3032710	WA14577	2,480.4
COMP. BLEED VALVE	3100829-03	39A152	2,480.4
Key: TBA = To be assigned, N/A = Not Applicable			

Comments: All engines ship FOB ATS dock.