



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-34AG	TSN:	11,236.6	TSO:	0.0	W/O#:	TBA
PCE:	52151	CSN:	13,110	CSO:	0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	A1564	16,510	2,490
Disk, 2 nd Stg.	3013712	14A166	20,332	3,668
Disk, 3 rd Stg.	3011713	22B159	19,781	5,219
Impeller	3013176	A9091	16,510	2,490
Disk, CT	3013411	8B724	12,261	3,739
PT Disk, 1 st Stg.	3022412	2L610	16,408	3,592

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	983056	0.0
FUEL PUMP	025323-101-02	7979	0.0
FUEL CONTROL UNIT	2524440-9-8-6	A25630	0.0
START FLOW CONTROL	3019109	13301	0.0
OIL/FUEL HEATER	10552E	1129	0.0
COMP. BLEED VALVE	3100829-03	8F793	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.