



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-34	TSN:	GG: 10,828.1 PS: 9,794.2	TSO:	GG: 0.0 PS: 1,164.2	W/O#:	TBA
PCE:	GG: RB0003 PS: 51005-100	CSN:	GG: 15,066 PS: 10,673	CSO:	GG: 0.0 PS: 2,772	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	5008	13,288	5,712
Disk, 2 nd Stg.	3013712	54A414	18,839	5,161
Disk, 3 rd Stg.	3011713	4T322	16,555	8,445
Impeller	3013176	7A461	13,110	5,890
Disk, CT	3013411	7P056	12,498	3,502
PT Disk, 1 st Stg.	3026812	15A141	14,600	5,400

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	14413784	1,164.2
FUEL PUMP	025323-101-03	14328	0.0
FUEL CONTROL UNIT	2524440-9-8	A7192	0.0
START FUEL CONTROL	3019109/25234-2	11909	0.0
OIL/FUEL HEATER	10552E	TBA	0.0
COMP. BLEED VALVE	3100829-03	7C353	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.

FINAL