



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-27I-28	TSN:	9,717.9	TSO:	0.0	W/O#:	TBA
PCE:	51316	CSN:	13,331	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	A3581	13,331	5,669
Disk, 2 nd Stg.	3013712	A6609	13,331	10,669
Disk, 3 rd Stg.	3011713	B3732	13,331	11,669
Impeller	3013176	A7853	13,331	5,669
Disk, CT	3013411	TBA	12,450	3,550
PT Disk, 1 st Stg.	3026812	A5942	13,331	6,669

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002	1440198K	0.0
FUEL PUMP	3034792	0278	0.0
FUEL CONTROL UNIT	2524440-9-8-6	A41695	0.0
START FLOW CONTROL	3019109	6708	0.0
OIL/FUEL HEATER	10552E	3332	0.0
COMP. BLEED VALVE	3100829-03	7C368	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.

 CT BLADE PN E3045741-01 (PMA) NEW