



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-34	TSN:	23,036	TSO:	0.0	W/O#:	TBD
PCE:	56485	CSN:	24,717	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	RWA14A052	13,123	5,877
Disk, 2 nd Stg.	3013712	13A408	15,936	8,064
Disk, 3 rd Stg.	3011713	9948	12,203	12,797
Impeller	3013176	CA0091	13,994	5,006
Disk, CT	3013411	8L474	12,296	3,074
PT Disk, 1 st Stg.	3022412	21A544	15,410	4,590

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-004-01	1573782	0.0
FUEL PUMP	025323-101-03	13028	0.0
FUEL CONTROL UNIT	3244777	TBA	0.0
START FUEL CONTROL	25234-3	13607	0.0
OIL/FUEL HEATER	10552E	4356	0.0
COMP. BLEED VALVE	3100829-03	5E820	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.