



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	60A	TSN:	4,376.4	TSO:	1,677.7	W/O#:	11200
PCE:	PK0486	CSN:	3,772	CSO:	1,491	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Rotor, Comp. 1 st Stg.	3041271	EAAD000K114	1,491	13,509
Disk, 2 nd Stg.	3034312	A001B6A4	3,772	16,228
Disk, 3 rd Stg.	3034313	A001BN75	3,772	16,228
Impeller	3036793	6H327	3,772	20,228
Disk, CT	3040311	A001APK3	3,772	11,228
PT Disk, 1 st Stg.	3029312	A001BY9D	4,913	25,087
PT Disk, 2 nd Stg.	3029313	A001BY9N	4,913	25,087

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-310	11453602	1,677.7
FUEL PUMP	825601-5	006290	1,677.7
FUEL CONTROL UNIT	8061-333	12343169	1,677.7
FLOW DIVIDER	26035-1	4599	1,994.7
OIL/FUEL HEATER	10585K	WA19380	1,677.7
COMP. BLEED VALVE	3117032-01	8T357	1,677.7

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.