



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

<b>Engine Rotor Sheet</b>							
PT6A:	<b>-27</b>	TSN:	<b>6,580.1</b>	TSO:	<b>2,661.5</b>	W/O#:	<b>11186</b>
PCE:	<b>P50882</b>	CSN:	<b>5,669</b>	CSO:	<b>3,056</b>	TSHS:	<b>0.0</b>

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3013111	8531	5,669	13,331
Disk, 2 <sup>nd</sup> Stg.	3013712	A2212	5,669	18,331
Disk, 3 <sup>rd</sup> Stg.	3011713	9148	5,669	19,331
Impeller	3013176	A6686	5,669	13,331
Disk, CT	3013411	A9116	5,669	10,331
PT Disk, 1 <sup>st</sup> Stg.	3022412	A3594	5,669	14,331

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-004-01	2131946	1,705.5
FUEL PUMP	025323-101	2421	2,661.5
FUEL CONTROL UNIT	2524440-9-6	A25952	1,676.0
START FLOW CONTROL	3019109	8470	210.7
OIL/FUEL HEATER	10552E	1513	2,661.5
COMP. BLEED VALVE	3100829-03	A413	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.