



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-114A	TSN:	13,533.3	TSO:	2,666.7	W/O#:	11698
PCE:	17405	CSN:	15,410	CSO:	3,320	TSHS:	800.8

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	1Y637	15,410	3,590
Disk, 2 nd Stg.	3013712	1A890	21,067	2,933
Disk, 3 rd Stg.	3011713	6487	22,222	2,778
Impeller	3027798	7E420	17,051	1,949
Disk, CT	3013411	1A045	15,558	442
PT Disk, 1 st Stg.	3026812	3Y010	19,324	676

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	2476713	2,666.7
FUEL PUMP	702801-5	0249	2,666.7
FUEL CONTROL UNIT	3244897-4	B10793	2,363.9
FLOW DIVIDER	3019906/25536-4	12855	2,666.7
OIL/FUEL HEATER	10552E	1276	2,666.7
COMP. BLEED VALVE	3049038-03	GA1151	2,666.7

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.

INITIAL

As returned from loan. Westwind