



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

<b>Engine Rotor Sheet</b>							
PT6A:	<b>-21</b>	TSN:	GG: 2,292 PS: 2,292	TSO:	GG: N/A PS: 1,136	W/O#:	<b>11670</b>
PCE:	<b>PE0663</b>	CSN:	GG: 2,514 PS: 2,514	CSO:	GG: N/A PS: 1,039	TSHS:	<b>0.0</b>

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3013111	RWA14A062	2,514	16,486
Disk, 2 <sup>nd</sup> Stg.	3013712	A001RKPE	2,514	21,486
Disk, 3 <sup>rd</sup> Stg.	3011713	A001T027	2,514	22,486
Impeller	3013176	EAAA000L518	2,514	16,486
Disk, CT	3013411	A001T9W3	2,514	13,486
PT Disk, 1 <sup>st</sup> Stg.	3026812	A001RTH1	2,514	17,486

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-025-01	1815206	0.0
FUEL PUMP	386101-5	002316	2,292.0
FUEL CONTROL UNIT	3244745-3	A33304	0.0
FLOW DIVIDER	3036640	3132	3,980.0
OIL/FUEL HEATER	10552E	WA22628	2,292.0
COMP. BLEED VALVE	3100829-03	1R268	1,156.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.