



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-27/-28	TSN:	10,448.1	TSO:	0.0	W/O#:	10505
PCE:	50888	CSN:	14,061	CSO:	0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	9610	14,061	4,939
Disk, 2 nd Stg.	3013712	A2339	14,061	9,939
Disk, 3 rd Stg.	3011713	9202	14,061	10,939
Impeller	3013176	A6678	14,061	4,939
Disk, CT	3013411	TBD	4,380	11,620
PT Disk, 1 st Stg.	3022412	A3550	14,061	5,939

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	TBD	TBD	TBD
FUEL PUMP	356100	1138	0.0
FUEL CONTROL UNIT	2524440-7-6	A89473	0.0
START FLOW CONTROL	SFC113	8267	0.0
OIL/FUEL HEATER	10552E	1934	0.0
COMP. BLEED VALVE	3100829-03	3H321	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.