



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-27/-28	TSN:	13,041.3	TSO:	0.0	W/O#:	TBA
PCE:	PG0091	CSN:	23,305	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	RWA14A052	13,123	5,877
Disk, 2 nd Stg.	3013712	51B596	17,710	6,290
Disk, 3 rd Stg.	3011713	4821	20,301	4,699
Impeller	3013176	A3329	14,046	4,954
Disk, CT	3013411	8L579	12,926	3,074
PT Disk, 1 st Stg.	3026812	A000118A	8,122	11,878

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-004-01	1758015	0.0
FUEL PUMP	386101-5	001634	0.0
FUEL CONTROL UNIT	2524440-7-6	A59800	0.0
FLOW DIVIDER	3019109	7156	0.0
OIL/FUEL HEATER	10552E	1732	0.0
COMP. BLEED VALVE	3100829-03	34A700	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.