



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

<b>Engine Rotor Sheet</b>							
PT6A:	-27	TSN:	13,837.2	TSO:	2,009	W/O#:	N/A
PCE:	40613	CSN:	16,740	CSO:	1,684	TSHS:	359.8

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3013111	3521	16,740	2,260
Disk, 2 <sup>nd</sup> Stg.	3013712	6342	16,740	7,260
Disk, 3 <sup>rd</sup> Stg.	3011713	4857	16,740	8,260
Impeller	3013176	A1300	16,740	2,260
Disk, CT	3013411	A0001P9P	15,407	593
PT Disk, 1 <sup>st</sup> Stg.	3026812	A000L53W	16,097	3,903

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROP GOVERNOR	8210-004-01	1485575	939.9
FUEL PUMP	025323-101	1203D	2,009
FUEL CONTROL UNIT	2524440-9-8-6	A74812	2,152.4
START FLOW CONTROL	3019109	13811	2,009
OIL/FUEL HEATER	10552E	WA2312	2,009
COMP. BLEED VALVE	3100829-03	12A404	2,009

Key: TBA = To be assigned, N/A = Not Applicable      Serial numbers are subject to change.

Comments: All engines ship FOB ATS dock.