



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-28	TSN:	GG: 29,494.5 PS: 26,510.6	TSO:	GG: 3,321.7 PS: 3,321.7	W/O#:	TBA
PCE:	GG: 50047 PS: 50047	CSN:	GG: 31,584 PS: 28,681	CSO:	GG: 3,870 PS: 3,870	TSHS:	16.2

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	34B657	12,663	6,337
Disk, 2 nd Stg.	3013712	A1102	17,937	6,063
Disk, 3 rd Stg.	3011713	A001PY0K	18,220	6,780
Impeller	3013176	EAAB000C103	17,380	1,620
Disk, CT	3013411	8X130	13,186	2,814
PT Disk, 1 st Stg.	3022412	A3754	18,833	1,167

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	1284812	3,321.7
FUEL PUMP	025323-101-03	10165	3,321.7
FUEL CONTROL UNIT	2524440-7-6	A-74994	3,321.7
START FLOW CONTROL	3019109/25234-5	9959538014	3,321.7
OIL/FUEL HEATER	10552E	WA14100	3,321.7
COMP. BLEED VALVE	3100829-03	6C927	3,321.7

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.