



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-28	TSN:	757.2	TSO:	N/A	W/O#:	TBD
PCE:	51790	CSN:	852	CSO:	N/A	TSHS:	N/A

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	6A790	852	18,148
Disk, 2 nd Stg.	3013712	5A030	852	23,148
Disk, 3 rd Stg.	3011713	5A267	852	24,148
Impeller	3013176	2A126	852	18,148
Disk, CT	3013411	7A140	852	15,148
PT Disk, 1 st Stg.	3022412	5A851	852	19,148

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	TBA	TBA	TBA
FUEL PUMP	025323-101-02	4076D	757.2
FUEL CONTROL UNIT	2524440-5	A74157	757.2
START FLOW CONTROL	TBA	TBA	TBA
OIL/FUEL HEATER	10552E	4503	757.2
COMP. BLEED VALVE	TBA	TBA	TBA
EXCITER BOX	TBA	TBA	TBA

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.