



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-28	TSN:	11,956.5	TSO:	0.0	W/O#:	TBA
PCE:	PG0206	CSN:	10,708	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	77B115	10,708	8,292
Disk, 2 nd Stg.	3013712	A00196KF	10,708	13,292
Disk, 3 rd Stg.	3011713	A0019CLR	10,708	14,292
Impeller	3013176	TBA	10,708	8,292
Disk, CT	3013411	7E790	7,902	8,098
PT Disk, 1 st Stg.	3026812	A0019H37	10,708	9,292

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002	1441997	0.0
FUEL PUMP	386101-5	1752	0.0
FUEL CONTROL UNIT	2524440-8-6	A66205	0.0
START FLOW CONTROL	3019109	15458	0.0
OIL/FUEL HEATER	10552E	WA18997	0.0
COMP. BLEED VALVE	3100829-03	8C676	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.