



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-34	TSN:	16,729.8	TSO:	3,927.7	W/O#:	11005
PCE:	50385	CSN:	21,363	CSO:	6,284	TSHS:	259.9

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	82A069	17,082	1,918
Disk, 2 nd Stg.	3013712	7243	21,413	2,587
Disk, 3 rd Stg.	3011713	6855	21,413	3,587
Impeller	3013176	9C462	16,402	2,598
Disk, CT	3013411	A0001P9D	15,366	634
PT Disk, 1 st Stg.	3022412	A2603	12,920	7,080

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	2173961	530.2
FUEL PUMP	025323-101-02	4088	3,927.7
FUEL CONTROL UNIT	3244834-5-3-2	A74244	259.9
START FLOW CONTROL	3019109	11085	3,649.7
OIL/FUEL HEATER	10552E	384	3,927.7
COMP. BLEED VALVE	3100829-03	1A374	1,754.8

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.

FINAL