



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

<b>Engine Rotor Sheet</b>							
PT6A:	-34	TSN:	2,480.4	TSO:	NA	W/O#:	10908
PCE:	RB0075	CSN:	2,640	CSO:	NA	TSHS:	433.2

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3013111	65B527	2,640	16,360
Disk, 2 <sup>nd</sup> Stg.	3013712	A000BYKT	2,640	21,360
Disk, 3 <sup>rd</sup> Stg.	3011713	A000CB4N	2,640	22,360
Impeller	3013176	5H362	2,640	16,360
Disk, CT	3013411	A000C6HH	2,640	13,360
PT Disk, 1 <sup>st</sup> Stg.	3026812	A000C6LN	2,640	17,360

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-304	15267662	439.1
FUEL PUMP	3034794	1293	2,480.4
FUEL CONTROL UNIT	N/A	N/A	N/A
FLOW DIVIDER/DUMP VALVE	3019906/25536-4	16268	433.2
OIL/FUEL HEATER	3032710	WA14348	2,480.4
COMP. BLEED VALVE	3100829-03	35A580	2,480.4

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.