



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-34	TSN:	3,425.8	TSO:	NA	W/O#:	11776
PCE:	RB0075	CSN:	3,816	CSO:	NA	TSHS:	1,378.6

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	65B527	3,816	15,184
Disk, 2 nd Stg.	3013712	A000BYKT	3,816	20,184
Disk, 3 rd Stg.	3011713	A000CB4N	3,816	21,184
Impeller	3013176	5H362	3,816	15,184
Disk, CT	3013411	A000C6HH	3,816	12,184
PT Disk, 1 st Stg.	3026812	A000C6LN	3,816	16,184

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-304	15267662	1,384.5
FUEL PUMP	3034794	1293	3,425.8
FUEL CONTROL UNIT	2524440-9	C22313	2,992.6
START FLOW CONTROL	25234-5	15317	2,992.6
OIL/FUEL HEATER	3032710	WA14348	3,425.8
COMP. BLEED VALVE	3100829-03	SA55R	1,378.6

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.

Updated with rental log book sent back to ATS January 2025