



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-34AG	TSN:	5,389.2	TSO:	952.3	W/O#:	TBA
PCE:	PH0877	CSN:	Starts: 3,952 Flights: 9,289	CSO:	Starts: 443 Flights: 1,513	TSHS:	520.3

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	RWA78D615	2,158	16,842
Disk, 2 nd Stg.	3013712	A00393RP	6,676	17,324
Disk, 3 rd Stg.	3011713	A0038K8R	5,672	19,328
Impeller	3013176	EAAC000Y409	3,509	15,491
Disk, CT	3013411	YUAA012A744	7,850	8,150
PT Disk, 1 st Stg.	3026812	YUAA012A152	4,486	19,514

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	18479985	952.3
FUEL PUMP	386101-5	003673	952.3
FUEL CONTROL UNIT	4138008-3 MOD 4	C75985	952.3
FLOW DIVIDER/DUMP VALVE	3109906/25536-4	10936	520.3
OIL/FUEL HEATER	10552E	WA44237	952.3
COMP. BLEED VALVE	3075033	AHX1500504	952.3

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.
 As received from Aeroagripac