



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-34AG	TSN:	5,607.4	TSO:	1,170.5	W/O#:	TBA
PCE:	PH0877	CSN:	Starts: 4,065 Flights: 9,998	CSO:	Starts: 556 Flights: 2,222	TSHS:	738.5

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	RWA78D615	2,258	16,742
Disk, 2 nd Stg.	3013712	A00393RP	6,985	17,015
Disk, 3 rd Stg.	3011713	A0038K8R	5,934	19,066
Impeller	3013176	EAAC000Y409	3,727	15,273
Disk, CT	3013411	YUAA012A744	8,152	7,848
PT Disk, 1 st Stg.	3026812	YUAA012A152	4,658	19,342

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	18479985	1,170.5
FUEL PUMP	386101-5	003673	1,170.5
FUEL CONTROL UNIT	4138008-3 MOD 4	C75985	1,170.5
FLOW DIVIDER/DUMP VALVE	3109906/25536-4	10936	738.5
OIL/FUEL HEATER	10552E	WA44237	1,170.5
COMP. BLEED VALVE	3075033	AHX1500504	1,170.5

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.