



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-45R	TSN:	12,541.4	TSO:	0.0	W/O#:	8428
PCE:	84329	CSN:	13,460	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3021911	1P197	13,460	6,540
Disk, 2 nd Stg.	3023112	2P352	13,460	6,540
Disk, 3 rd Stg.	3023113	2P453	13,460	6,540
Impeller	3017463	2C335	13,460	6,540
Disk, CT	3024711	3P354	13,460	6,540
PT Disk, 1 st Stg.	3029312	1P359	13,460	16,540
PT Disk, 2 nd Stg.	3029313	1P462	13,460	16,540

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-209F	1994504	0.0
FUEL PUMP	399701-5	0215	0.0
FUEL CONTROL UNIT	3244773-5-4	A44013	0.0
OIL/FUEL HEATER	10585F	1115	0.0
COMP. BLEED VALVE	3100922-08	6C582	0.0
COMP. BLEED VALVE	3100922-05	B0226	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.