



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-34	TSN:	18,337.9	TSO:	0.0	W/O#:	10969
PCE:	51008	CSN:	25,299	CSO:	0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	RWA14A052	13,123	5,877
Disk, 2 nd Stg.	3013712	8E779	13,486	10,514
Disk, 3 rd Stg.	3011713	9948	12,203	12,797
Impeller	3013176	2D973	10,505	8,495
Disk, CT	3013411	8L474	12,296	3,074
PT Disk, 1 st Stg.	3022412	21A544	15,410	4,590

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	1715639	0.0
FUEL PUMP	025323-101-03	12376	0.0
FUEL CONTROL UNIT	2524440-7-6	A74157	0.0
FLOW DIVIDER/DUMP VALAVE	3019906/25536-4	7869	0.0
OIL/FUEL HEATER	10552E	WA12126	0.0
COMP. BLEED VALVE	3100829-03	1A161	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.