



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-41	TSN:	14,696.1	TSO:	0.0	W/O#:	10511
PCE:	80737	CSN:	16,037	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3021911	A4683	16,037	3,963
Disk, 2 nd Stg.	3023112	82A607	10,201	9,799
Disk, 3 rd Stg.	3023113	B6791	16,037	3,963
Impeller	3017463	B1402	16,037	3,963
Disk, CT	3049291-01	A0022BAD	6,499	3,501
PT Disk, 1 st Stg.	3029312	87A631	5,785	24,215
PT Disk, 2 nd Stg.	3029313	18B980	9,931	20,061

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-007F	2171366	0.0
FUEL PUMP	025323-300-03	5725	0.0
FUEL CONTROL UNIT	3244755-23	A62694	0.0
FLOW DIVIDER	25536-4	5589	0.0
OIL/FUEL HEATER	10585K-J	274	0.0
HP COMP. BLEED VALVE	3100922-05	B1229	0.0
LP COMP. BLEED VALVE	3100923-02	3K266	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.