



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

<b>Engine Rotor Sheet</b>							
PT6A:	<b>114A</b>	TSN:	<b>21,562.9</b>	TSO:	<b>0.0</b>	W/O#:	<b>N/A</b>
PCE:	<b>19177</b>	CSN:	<b>19,842</b>	CSO:	<b>0.0</b>	TSHS:	<b>0.0</b>

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3013111	24A827	17,147	1,853
Disk, 2 <sup>nd</sup> Stg.	3013712	3B669	20,588	3,412
Disk, 3 <sup>rd</sup> Stg.	3011713	4T445	22,256	2,744
Impeller	3027798	TXA1A4580	17,808	1,192
Disk, CT	3013411	64A251	6,341	1,659
PT Disk, 1 <sup>st</sup> Stg.	3026812	5T651	18,779	1,221

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROP GOVERNOR	8210-002-01	2457030	0.0
FUEL PUMP	702801-5	0168	0.0
FUEL CONTROL UNIT	3244897-4	C25046	0.0
FLOW DIVIDER	25536-4	19934	0.0
OIL/FUEL HEATER	10552E	385	0.0
COMP. BLEED VALVE	3049038-03	3489	0.0

Key: TBA = To be assigned, N/A = Not Applicable      Serial numbers are subject to change.

Comments: All engines ship FOB ATS dock.

1st, 2nd, 3rd Stock  
 Impeller Original  
 CT Stock  
 PT Stock