



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-34	TSN:	16,814.8	TSO:	0.0	W/O#:	TBD
PCE:	50385	CSN:	21,629	CSO:	0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	RWA61F042	5,232	13,768
Disk, 2 nd Stg.	3013712	3H548	7,437	16,563
Disk, 3 rd Stg.	3011713	5F609	7,437	17,563
Impeller	3013176	EAAB000P821	5,193	13,807
Disk, CT	3013411	98A040	8,602	7,398
PT Disk, 1 st Stg.	3026812	A001EFCB	12,718	7,282

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-003	1451926	0.0
FUEL PUMP	025323-101-03	8859	0.0
FUEL CONTROL UNIT	3244834-1	A66144	0.0
START FLOW CONTROL	25234-2	11573	0.0
OIL/FUEL HEATER	10552E	WA14579	0.0
COMP. BLEED VALVE	3100829-03	4E650	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.