



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

<b>Engine Rotor Sheet</b>							
PT6A:	<b>-21</b>	TSN:	<b>7,117.4</b>	TSO:	<b>0.0</b>	W/O#:	<b>TBA</b>
PCE:	<b>25520</b>	CSN:	<b>8,882</b>	CSO:	<b>0</b>	TSHS:	<b>0.0</b>

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3013111	1Y824	8,882	10,118
Disk, 2 <sup>nd</sup> Stg.	3013712	20A035	8,882	15,118
Disk, 3 <sup>rd</sup> Stg.	3011713	18A298	8,882	16,118
Impeller	3013176	3D062	8,882	10,118
Disk, CT	3013411	YUAA008A630	3,623	12,377
PT Disk, 1 <sup>st</sup> Stg.	3022412	10A462	8,882	11,118

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-025G	1746789G	0.0
FUEL PUMP	025323-101-03	14060	0.0
FUEL CONTROL UNIT	3244745-3	A75906	0.0
FLOW DIVIDER	3036640	3132	0.0
OIL/FUEL HEATER	10552E	4740	0.0
COMP. BLEED VALVE	3100829-03	6T785	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.