



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-34AG	TSN:	9,693.6	TSO:	0.0	W/O#:	11281
PCE:	50949	CSN:	9,990	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	9772	10,051	8,950
Disk, 2 nd Stg.	3013712	A1897	10,051	13,950
Disk, 3 rd Stg.	3011713	B1635	10,051	14,950
Impeller	3013176	A8337	10,051	8,950
Disk, CT	3013411	A0019PLX	7,914	8,086
PT Disk, 1 st Stg.	3022412	A3366	10,025	9,975
Key: TBA = To be assigned, N/A = Not Applicable				

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-004-01	1995337	0.0
FUEL PUMP	025323-101-03	4735	0.0
FUEL CONTROL UNIT	2524440-7-6	A41294	0.0
START FLOW CONTROL	25234-2	8494	0.0
OIL/FUEL HEATER	10552E	WA8668	0.0
COMP. BLEED VALVE	3100829-03	A6863	0.0
Key: TBA = To be assigned, N/A = Not Applicable			

Comments: All engines ship FOB ATS dock.