



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

<b>Engine Rotor Sheet</b>							
PT6A:	<b>-34AG</b>	TSN:	<b>5,719</b>	TSO:	<b>1,282.1</b>	W/O#:	<b>TBA</b>
PCE:	<b>PH0877</b>	CSN:	Starts: 4,223 Flights: 11,188	CSO:	Starts: 714 Flights: 3,412	TSHS:	<b>850.1</b>

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3013111	RWA78D615	2,415	16,585
Disk, 2 <sup>nd</sup> Stg.	3013712	A00393RP	7,469	16,531
Disk, 3 <sup>rd</sup> Stg.	3011713	A0038K8R	6,346	18,654
Impeller	3013176	EAAC000Y409	4,084	14,916
Disk, CT	3013411	YUAA012A744	8,609	7,391
PT Disk, 1 <sup>st</sup> Stg.	3026812	YUAA012A152	4,920	19,081

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	18479985	1,282.1
FUEL PUMP	386101-5	003673	1,282.1
FUEL CONTROL UNIT	4138008-3 MOD 4	C75985	1,282.1
FLOW DIVIDER/DUMP VALVE	3109906/25536-4	10936	850.1
OIL/FUEL HEATER	10552E	WA44237	1,282.1
COMP. BLEED VALVE	3075033	AHX1500504	1,282.1

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.