



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-27I-28	TSN:	14,261.4	TSO:	0.0	W/O#:	TBA
PCE:	50286	CSN:	16,851	CSO:	0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	85B315	7,914	11,086
Disk, 2 nd Stg.	3013712	A0019CM8	7,914	16,086
Disk, 3 rd Stg.	3011713	A0019KKE	7,914	17,086
Impeller	3013176	5C141	10,732	8,268
Disk, CT	3013411	8L593	9,388	6,612
PT Disk, 1 st Stg.	3022412	5B480	12,089	7,911

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROP GOVERNOR	8210-004-01	1700521	0.0
FUEL PUMP	025323-101-03	8160	0.0
FUEL CONTROL UNIT	2524440-9	C7172	0.0
START FLOW CONTROL	3019109	6906	0.0
OIL/FUEL HEATER	10552E	599	0.0
COMP. BLEED VALVE	3100829-03	AHX003310	0.0

Key: TBA = To be assigned, N/A = Not Applicable Serial numbers are subject to change.

Comments: All engines ship FOB ATS dock.