



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-34AG	TSN:	12,436.6	TSO:	0.0	W/O#:	TBA
PCE:	PH0219	FSN:	33,741	SSN:	3,335	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	63B691	6,173	12,827
Disk, 2 nd Stg.	3013712	9L357	9,404	14,596
Disk, 3 rd Stg.	3011713	7L770	9,404	15,596
Impeller	3013176	9C460	7,863	11,137
Disk, CT	3013411	30A83A5526	12,043	3,957
PT Disk, 1 st Stg.	3026812	A0017R3C	10,033	9,967

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	12234704	0.0
FUEL PUMP	3034794	002665	0.0
FUEL CONTROL UNIT	3244834-4-3-2	A59856	0.0
FLOW DIVIDER/DUMP VALVE	3109906	4256	0.0
OIL/FUEL HEATER	10552E	863	0.0
COMP. BLEED VALVE	3100829-03	A34277	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.