



Airforce Turbine Service
www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-21	TSN:	6,182.8	TSO:	0.0	W/O#:	11695
PCE:	25098	CSN:	9,404	CSO:	0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	4A831	16,394	2,606
Disk, 2 nd Stg.	3013712	A00166WE	20,936	3,064
Disk, 3 rd Stg.	3011713	6M863	19,538	4,462
Impeller	3013176	1A688	16,394	2,606
Disk, CT	3013411	30A346	15,532	468
PT Disk, 1 st Stg.	3022412	50B346	17,619	2,381
Key: TBA = To be assigned, N/A = Not Applicable				

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-AF	1436238	0.0
FUEL PUMP	3031709	3923	0.0
FUEL CONTROL UNIT	3244745-3	A72801	0.0
FLOW DIVIDER	3019906/25536-4	L0430	0.0
OIL/FUEL HEATER	10552E	1163	0.0
COMP. BLEED VALVE	3100829-03	AHX08684	0.0
Key: TBA = To be assigned, N/A = Not Applicable			

Comments: All engines ship FOB ATS dock.