



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-27/-28	TSN:	14,322.3	TSO:	0.0	W/O#:	TBA
PCE:	52419	CSN:	18,094	CSO:	0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	65B691	6,173	12,827
Disk, 2 nd Stg.	3013712	45B417	11,316	12,684
Disk, 3 rd Stg.	3011713	45B393	10,043	14,957
Impeller	3013176	8H539	7,356	11,644
Disk, CT	3013411	39B667	13,825	2,175
PT Disk, 1 st Stg.	3022412	A0001XK9	13,137	6,863

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	1284812	0.0
FUEL PUMP	025323-101-03	10165	0.0
FUEL CONTROL UNIT	2524440-7-6	A-74994	0.0
START FLOW CONTROL	3019109/25234-5	9959538014	0.0
OIL/FUEL HEATER	10552E	WA14100	0.0
COMP. BLEED VALVE	3100829-03	6C927	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: