



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-135	TSN:	7,994.4	TSO:	0.0	W/O#:	7666
PCE:	92468	CSN:	6,689	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	7K285	6,689	12,311
Disk, 2 nd Stg.	3013712	6K682	6,689	17,311
Disk, 3 rd Stg.	3011713	4K452	6,689	18,311
Impeller	3013176	5B520	6,689	12,311
Disk, CT	3024211	3K990	6,689	9,311
PT Disk, 1 st Stg.	3022312	1K681	6,689	23,311

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-003	1586492M-U	0.0
FUEL PUMP	025323-101-03	10407	0.0
FUEL CONTROL UNIT	3244777-1	A85200	0.0
START FLOW CONTROL	25234-2	12909	0.0
OIL/FUEL HEATER	10552E	204	0.0
COMP. BLEED VALVE	3100829-03	9F251	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.