



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-27/-28	TSN:	GG: 34,271.4 PS: 28,119.4	TSO:	GG: 3,184 PS: 3,206.4	W/O#:	6898
PCE:	GG: 42038 PS: 40975-100	CSN:	GG: 49,260 PS: 41,488	CSO:	GG: 3,856 PS: 3,878	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	63B821	12,405	6,595
Disk, 2 nd Stg.	3013712	A0009MN1	12,405	11,595
Disk, 3 rd Stg.	3011713	A0009B50	12,405	12,595
Impeller	3013176	5H214	12,405	6,595
Disk, CT	3013411	A000B833	13,127	2,873
PT Disk, 1 st Stg.	3022412	8N093	12,546	7,454
CT Blades	T102401-792	N/A	NEW	

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-003U	1826799	3,206.4
FUEL PUMP	025323-101-03	6714	3,184
FUEL CONTROL UNIT	2524440-7-6	A59863	3,184
START FLOW CONTROL	3019109	11100	3,184
OIL/FUEL HEATER	10552E	2361	3,184
COMP. BLEED VALVE	3100829-03	25A202	3,184

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.