



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-27I-28	TSN:	13,828.8	TSO:	0.0	W/O#:	7605
PCE:	50064	CSN:	12,781	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	0605	12,781	6,219
Disk, 2 nd Stg.	3013712	4711	12,781	11,219
Disk, 3 rd Stg.	3011713	3524	12,781	12,219
Impeller	3013176	A0444	12,781	6,219
Disk, CT	3013411	0763	12,713	3,287
PT Disk, 1 st Stg.	3012812	7062	12,781	7,219

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002	12091081	0.0
FUEL PUMP	025323-101-03	12961	0.0
FUEL CONTROL UNIT	3524440-7	C7054	0.0
START FLOW CONTROL	3019109	6914	0.0
OIL/FUEL HEATER	10552	3692	0.0
COMP. BLEED VALVE	3100829-03	2C221	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.